



| | | | E2.2L | E2.2LS | | | | E2.2L | E2.2LS |
|------|--------|-----------------------------------|-------|--------|------|--------|--------------------------|-------|--------|
| ITEM | PART # | MATERIAL | QTY | QTY | ITEM | PART # | MATERIAL | QTY | QTY |
| c | 9373 | Bolt, Machine 3/4" X Req'd Length | 2 | 2 | at | 4205 | Guy Marker | 1 | |
| d | 9093 | Washer, Curved 3" X 13/16" | 2 | 2 | at | 4206 | Scratcher, Cattle | | 1 |
| p | | Connector, As Req'd | | | ci | 9340 | Clevis, Thimble | 1 | 1 |
| u | 9017 | Guy Deadend, 3/8" Preformed | 2 | 2 | cj | 3011 | Wire, Cu Jacketed Ground | 5' | 5' |
| v | 9243 | Pole Eye Plate | 1 | 1 | ck | 9013 | Guy Bonding Anchor | 1 | 1 |
| y | 4180 | Wire, Guy Strand 3/8" | 50' | 50' | ek | 9097 | Locknut, 3/4" | 2 | 2 |

DESIGN PARAMETERS:

Maximum Working Load = Lesser of 10,000 lbs. Horizontal or allowable guy wire tension

**SINGLE DOWN GUY
POLE EYE PLATE TYPE
LARGE CONDUCTORS**

RUS
10/10/23
REV. 0



E2.2L, E2.2LS